



Commercial Invoice

CINV27256-1

Invoice Date: 1/21/2026

| SHIP FROM: Boulder Imaging Inc. 400 Centennial Parkway, Suite 100 Louisville, CO 80027 Contact: Jacob Dorward T: 720-545-0966 E: jdorward@boulderimaging.com | | | | NOTIFY PARTY (IF DIFFERENT THAN SHIP TO): "NOMAC SIRDARYA OPERATION AND MAINTENANCE 108, Buyuk Turon Street, ACM A.Temur, Shirin city, Sirdarya region, Republic of Uzbekistan Contact Person: Mr. Shahan Khan Mobile: +971 56 688 5059 Email: shahan.khan@nomac.com | | | SHIP TO: FE "ACWA POWER BASH WIND" LLC 71 Ogitma str., Kukcha MFY, Gijduvan district, Bukhara Region, Republic of Uzbekistan, 100084 Contact Person: Mr. Nodirbek Makhmudov Mobile: +998994608010 Email: nodirbek.makhmudov@nomac.com | | |
|---|---------|-------|------|---|-------------|-------------------------------------|--|--|--|
| Ship Date | Carrier | Terms | Mode | Main Description | IDI Job No. | Sales Order # | Country of Origin | | |
| 1/30/2026 | DHL | DAP | AIR | BASH PROJECT - WARRANTY REPLACEMENT STEREO IMAGER SUB SYSTEM FOR IDF STATION BSH14-41; WFOV CAMERA AND SWITCH FOR IDF STATION BSH12-40; PTU FOR IDF STATION IDF-3; WFOV CAMERA FOR IDF STATION B06-03 | 27256 | 27256-1, 27256-4, 27256-5, 27256-21 | USA | | |

| Item No. | No. of Pkgs | Pkg Type | Pkg Weight (kg) | Description | Harmonized Code | Qty | UOM | Unit Value | Total Value |
|--------------|-------------|----------|-----------------|---|--|-----|------|--------------|--------------|
| PL27256-1-01 | 1 of 2 | BOX | 14.5 | P/N - 105232 Assy, Stereo Imager Sub-System Goods supplied free of charge as replacement stock for defective goods – value supplied for Customs purposes only ECCN: NLR / 6A993 | USA Schedule B Code: 9015.40.0000 Uzbekistan HS Code: 8501 40 800 9 | 1 | each | \$ 21,948.36 | \$ 21,948.36 |
| PL27256-1-02 | 1 of 2 | BOX | 14.5 | P/N - 105231 Assy, WFOV Switch Goods supplied free of charge as replacement stock for defective goods – value supplied for Customs purposes only ECCN: NLR / 5A991 | USA Schedule B Code: 8536.90.8085 | 1 | each | \$ 1,070.66 | \$ 1,070.66 |
| PL27256-1-03 | 1 of 2 | BOX | 14.5 | P/N - 105224 Assy, WFOV Camera Enclosure Goods supplied free of charge as replacement stock for defective goods – value supplied for Customs purposes only ECCN: NLR / 6A993 (Serial Numbers: 25244672, 25244731) | USA Schedule B Code: 9015.80.2000 | 2 | each | \$ 3,541.78 | \$ 7,083.56 |
| PL27256-1-04 | 2 of 2 | BOX | 13.2 | P/N - 105220 Assy, PTU Sub-System, v4.8 Goods supplied free of charge as replacement stock for defective goods – value supplied for Customs purposes only ECCN: NLR / EAR99 (Serial Number: OV200492412006) | USA Schedule B Code: 8483.90.9500 Uzbekistan HS Code: 8501 53 501 0 | 1 | each | \$ 10,415.90 | \$ 10,415.90 |

| | | |
|------------------------|-----------------------|-----------------------------|
| Shipping Totals | Total Packages | Total (Gross) Weight |
| 2 | BOX | 27.7kg |

Subtotal \$ 40,518.48

Total Commercial Invoice Value: \$ 40,518.48

| |
|---|
| Declaration Statement: |
| I hereby certify that the information on this invoice is true and correct and the contents and value of this shipment is as stated above. Goods supplied free of charge as replacement stock for defective goods – value supplied for Customs purposes only. Items originated in the USA. |
| Reason for Export: WARRANTY REPLACEMENT |

NOTE:
All materials should be inspected to ensure correct quantities have been delivered and all materials are in good condition. After inspection and documentation, the packing list must be signed and returned to the IDI main office within 5 working days. Please notify your supervisor immediately if materials are found to be damaged, defective, or missing as well as note the damage on the packing list.