



Missing parts and or damage to the equipment must be reported within 4 hours of delivery.

Client: Matrif Metrology SA de CV		Address: Lago Luise #117 Residencial los Lagos	
Customer: Estefania Castillo		San Luis Potosí, SLP CP 78397	
PO#		Tel. 472 192 2365	
Item		Qty Shipped	Qty Returned
Magie base case		1	
ACQUIP Magnetic Base S/N AM1220B9		1	
5" Extension Tube		1	
Additional Notes:			
Operational Checks Lenin Rivera Completed By/Date: 10/03//24		Pass	Pass
		Fail	Fail
Date Shipped: 10/04//24	Date Returned:	Initials:	L.R.

info@acquip.com

+1 305.538.7101

PO BOX 191502 - Miami Beach FL 33119 - USA

acquip.com